

PUBLIC WORKS DEPARTMENT

No: EE/KV2/SIM6/21-22/2412 Date 7.12.2021

To :

The Authorised Signatory,
Sri Lakshmi Siddeshwara
Educational Trust (R)
SLS International Gurukul,
K.Channasandra, Bangalore

Sir,

Sub : Issue of Building Security letter.

Ref : 5) Your Office letter dated 7.11.2021
6) Letter No.566-67 dated 16.11.2021 of Assistant
Executive Engineer, No.9, Building Sub Division,
Bangalore

= = =

With reference to above subject, you have sought for building Security Certificate in respect of Sri Lakshmi Siddeshwara Educational Trust, SLS International Gurukul, K.Channasandra, Bangalore vide letter under Ref (1).

Accordingly spot inspection of the said School Building was done on 27.11.2021 in the presence of Executive Engineer, No.9, Building Sub Division and the details are furnished below as per letter under Ref (2).

- Joint verification of the building of Sri Lakshmi Siddeshwara Educational Trust, SLS International Gurukul, K.Channasandra, Bangalore was done on 27.11.2021.
- Said building has ground and three floors having stair case, toilet facility is made in the building as per the guidelines. There is drinking water facility.



Translated From: *[Signature]*
To: *[Signature]*
S.K. SUDHA
Typist/Translator
City Civil Court Typing Pool
BANGALORE, Mob: 99166 83927

- Aptitude Certificate has been obtained from BBMP.
- Principal of the School has confirmed that building plan and sketch have been issued and the building has been constructed accordingly.
- Building capacity and strength of concrete (NDT test) has been verified by the ASWE, Construction and Engineering, LLP No.1/1, 1st Cross, 4th Main, Padarayanapura, Hammer test and ultrasonic pulse velocity test have been obtained and confirmed that the building is in good condition.
- Said building comes under Zone-1.

On verification of all the documents given by Sri Lakshmi Siddeshwara Educational Trust, SLS International Gurukul, K.Channasandra, Bangalore and considering the Certificate issued that the said building is safety and secured, on verification of the building by the Public works technical team it is found on the testing reports that the building is "Structurally stable" after verifying said building, the undersigned has given no objection letter for the year 2021-22 that the building is "structurally stable".

Yours faithfully

Sd/-


Executive Engineer,
No.2, Building Section ,
Bangalore

Translated From:.....

To:.....

S. K. SUDHA

Typist / Translator
City Civil Court Typing Pool
BANGALORE, Mob: 99166 83922



ATTESTED BY ME

ANITHA BAI
ADVOCATES & NOTARY
Ganappa Enterprises, No. 134, Old 210
Pipeline Road, Ramanjaneya Temple
Abbigere, Bangalore - 560 092

26 MAR 2022



ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರ ಕಛೇರಿ
ನಂ.2ನೇ ಕಟ್ಟಡಗಳ ವಿಭಾಗ, ಕೆ.ಆರ್.ಸರ್ಕಾರಿ
ಬೆಂಗಳೂರು
ಸಂಖ್ಯೆ:ಕಾರ್ಯಪಾಲಕ-2:ಸಿಂ-6:21-22/2412

ದೂರವಾಣಿ 22122856, ಫ್ಯಾಕ್ಸ್ 080-22123368
e-mail eeblno2@gmail.com

ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ

ದಿನಾಂಕ:07/12/2021

ಇವರಿಗೆ:

The Authorized Signatory,
Sri Lakshmi Siddeshwara Educational Trust,
SLS International Gurukul,
K. Channasandra, Bangalore.

ಮಾನ್ಯರೇ,

ವಿಷಯ	ಕಟ್ಟಡ ಸುರಕ್ಷತಾ ಪತ್ರ ನೀಡುವ ಬಗ್ಗೆ.
ಉಲ್ಲೇಖ	5) ತಮ್ಮ ಕಛೇರಿ ಪತ್ರ ದಿನಾಂಕ 07-11-2021 6) ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು, ನಂ.9ನೇ ಕಟ್ಟಡಗಳ ಉಪವಿಭಾಗ, ಬೆಂಗಳೂರು ರಸ್ತೆ ಕಛೇರಿ ಪತ್ರ ಸಂಖ್ಯೆ:566-67:ದಿನಾಂಕ16-11-2021

ಮೇಲ್ಕಂಡ ವಿಷಯಕ್ಕೆ ಸಂಬಂಧಿಸಿದಂತೆ, Sri Lakshmi Siddeshwara Educational Trust, SLS International Gurukul, K. Channasandra, Bangalore, ಕಟ್ಟಡದ ಸುರಕ್ಷತಾ ಪ್ರಮಾಣ ಪತ್ರವನ್ನು ನೀಡುವಂತೆ ಉಲ್ಲೇಖ (1) ರ ಪತ್ರದಲ್ಲಿ ಕೋರಿರುತ್ತೀರಿ.


ಅದರಂತೆ, ಸದರಿ ಶಾಲಾ ಕಟ್ಟಡವನ್ನು ಸಂಬಂಧಪಟ್ಟ ದಾಖಲೆಗಳೊಂದಿಗೆ ದಿನಾಂಕ 27-11-2021 ರಂದು ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು, ನಂ.9ನೇ ಕಟ್ಟಡಗಳ ಉಪವಿಭಾಗ ರವರ ಉಪಸ್ಥಿತಿಯಲ್ಲಿ ಸ್ಥಳ ಪರಿಶೀಲಿಸಲಾಯಿತು. ಈ ಕೆಳಕಂಡಂತೆ ವಿವರಣೆಗಳನ್ನು ಉಲ್ಲೇಖ (2)ರ ಪತ್ರದಲ್ಲಿ ನೀಡಿರುತ್ತಾರೆ.

- Sri Lakshmi Siddeshwara Educational Trust, SLS International Gurukul, K. Channasandra, Bangalore, ರವರ ಕಟ್ಟಡವನ್ನು ದಿನಾಂಕ:27-11-2021 ರಂದು ಜಂಟಿ ಪರಿವೀಕ್ಷಣೆ ಕೈಗೊಳ್ಳಲಾಗಿರುತ್ತದೆ.
- ಕಟ್ಟಡವು ನೆಲಮಹಡಿ ಹಾಗೂ ಮೂರನೇ ಮಹಡಿಗಳನ್ನು ಒಳಗೊಂಡಿದ್ದು, ಮೆಟ್ಟಿಲುಗಳನ್ನು ಹಾಗೂ ಕಟ್ಟಡದಲ್ಲಿ ಶೌಚಾಲಯದ ವ್ಯವಸ್ಥೆಯನ್ನು ಮಾರ್ಗಸೂಚಿಯನ್ವಯ ನಿರ್ಮಿಸಲಾಗಿರುತ್ತದೆ. ಹಾಗೂ ಕುಡಿಯುವ ನೀರಿನ ವ್ಯವಸ್ಥೆ ಕಲ್ಪಿಸಲಾಗಿರುತ್ತದೆ.
- ಕಟ್ಟಡದ ಯೋಗ್ಯತಾ ಪ್ರಮಾಣ ಪತ್ರವನ್ನು ಬಿ.ಬಿ.ಎಂ.ಇ ವತಿಯಿಂದ ಪಡೆಯಲಾಗಿರುತ್ತದೆ.
- ಕಟ್ಟಡದ ನಕ್ಷೆ ಹಾಗೂ ವಿನ್ಯಾಸದ ನಕ್ಷೆಗಳನ್ನು ನೀಡಿದ್ದು, ಅದರಂತೆ ಕಟ್ಟಡವನ್ನು ನಿರ್ಮಿಸಲಾಗಿದೆ ಎಂದು ಶಾಲೆಯ ಪ್ರಾಂಶುಪಾಲರು ಧೃಢೀಕರಿಸಿರುತ್ತಾರೆ.
- ಕಟ್ಟಡದ ಸ್ಥಿರತೆಗಾಗಿ ಕಾಂಕ್ರೀಟ್ ಸದೃಢತೆಯನ್ನು ASWE, Construction & Engineering LLP, No.1/1, 1st Cross, 4th Main, Padarayanapura, Bangalore ವತಿಯಿಂದ ಪರಿಶೀಲಿಸಿ (NDT test,) Hammer

test and Ultrasonic pulse velocity test) ಪಡೆಯಲಾಗಿದ್ದು, ಕಟ್ಟಡವು ಸದೃಢವಾಗಿರುವುದಾಗಿ ಧೃಡೀಕರಿಸಲಾಗಿರುತ್ತದೆ.

- ಸದರಿ ಕಟ್ಟಡದ ಸ್ಥಳವು Zone-I ಗೆ ಸಂಬಂಧಿಸಿರುತ್ತದೆ.

ಸದರಿ ಸಂಸ್ಥೆಯವರು ನೀಡಿರುವ ಎಲ್ಲಾ ದಾಖಲೆಗಳನ್ನು ಪರಿಶೀಲಿಸಲಾಗಿ Sri Lakshmi Siddeshwara Educational Trust, SLS International Gurukul, K. Channasandra, Bangalore, ರವರ ಕಟ್ಟಡವು ರಚನಾತ್ಮಕವಾಗಿ ಸುರಕ್ಷಿತವಾಗಿದೆಯೆಂದು ನೀಡಿರುವ ಪ್ರಮಾಣ ಪತ್ರವನ್ನು ಪರಿಗಣಿಸಿ. ಹಾಗೂ ಕಟ್ಟಡವನ್ನು ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆಯ ತಾಂತ್ರಿಕ ತಂಡದಿಂದ ಪರಿಶೀಲಿಸಲಾಗಿ ಕಟ್ಟಡವು “ Structurally Stable” ಇರುವುದಾಗಿ ಪರೀಕ್ಷಾ ವರದಿಗಳಿಂದ ಕಂಡುಬಂದಿರುವುದರಿಂದ ಹಾಗೂ ಈ ಕೆಳಗೆ ಸಹಿ ಮಾಡಿರುವವರು ಪರಿವೀಕ್ಷಿಸಲಾಗಿ ಸದರಿ ಕಟ್ಟಡವು “ Structurally Stable” ಇದೆ ಎಂದು ನಿರಾಕ್ಷೇಪಣಾ ಪತ್ರವನ್ನು 2021-22ನೇ ಸಾಲಿಗೆ ನೀಡಲಾಗಿದೆ.

ತಮ್ಮ ವಿಶ್ವಾಸಿ,

ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು,

ನಂ.2ನೇ ಕಟ್ಟಡಗಳ ವಿಭಾಗ, ಬೆಂಗಳೂರು

